






Technical drawing of the 13/16"-28UN nut and washer assembly. The drawing includes a top view of the nut with a diameter of 30, a side view of the nut showing a height of 29 and a reference length of 53, and a top view of the washer with a diameter of 29. The nut is labeled 13/16"-28UN.



Packing:
#4 Zipper PE Bag.




 HTP ASIA TECHNOLOGY CO., LTD. 禾 凌 科 技 股 份 有 限 公 司			
	UNIT: mm	TITLE : RJ45 C Size Assembly Type For RJ45 & USB Plug Patch cable	
SCALE	1:1.5		
UNLESS OTHERWISE SPECIFIED TOLERANCES: XX. ± 1.0 .X ± 1.0 .XX ± 0.5 .XXX ± 0.25 ANGLE ± 1°		P/N: RUC-HSA	DR. SIBYL
			CH. JAMES
REV. A	SHEET 1/2	DWG.NO: RUC-HSA	AP.

機密 Installation Guide of RJ45 & USB Plug Patch Cable | RJ45 & USB Plug Patch Cable 組裝式安裝說明


Step 1: Pass the cable through the components 4.3.2 in sequence.

步驟 1: 將線材依序穿過部件 4, 3, 2。




Step 2: To screw out the hex nut of panel connector, then attach an extra piece of gasket, and lock the nut to the panel connector then install an extra gasket.

步驟 2: 先將板端連接器的六角螺帽退出, 然後裝上一片墊片後再將六角螺帽鎖上, 接著再裝上一片墊片。




Step 3: Insert the cable connector to panel connector

步驟 3: 將線端連接器插入板端連接器。



Step 4: Assemble components 2.3.4 in sequence.

步驟 4: 將部件 2, 3, 4 依序組裝。



HOLIN® HTP ASIA TECHNOLOGY CO., LTD. 禾 凌 科 技 股 份 有 限 公 司			
	UNIT:mm	TITLE : RJ45 C Size Assembly Type For RJ45 & USB Plug Patch cable	
SCALE	1:1.5		
UNLESS OTHERWISE SPECIFIED TOLERANCES: XX. ± 1.0 .X ± 1.0 .XX ± 0.5 .XXX ± 0.25 ANGLE ± 1°		P/N: RUC-HSA	DR. SIBYL
			CH. JAMES
REV. A	SHEET 2/2	DWG.NO: RUC-HSA	AP.